

Bandsaw

- Irregular curves
 - Ripping
 - Crosscutting
 - Resawing
1. Twisting, binding and pulling are the causes of broken blades
 2. Keep fingers and hands out of the kerf line at all times.
 3. No one should stand to the right of the saw while it is running.
 4. When backing out of a cut, stop the machine to prevent the blade from breaking or being pulled off the drive wheels.
 5. Small curves should be cut with a thin blade
 6. Round stock must be clamped in a locking device
 7. No adjustments are made while the saw is running.
 8. If the blade breaks, turn the machine off and wait for all moving parts to stop. Notify the instructor.
 9. Place small pieces in container behind the saw when finished
 10. The saw guard should be adjusted 1/8" above the wood
 11. When the saw has stopped, GENTLY lower the saw guide to the table
 12. Thick lumber must be cut a slow pace.
 13. Use relief cuts when necessary.